

NOV 13 1984

Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Mr. S. M. Hare of this office on May 29-31, August 13-14, and September 28, 1984, of activities at D. C. Cook Nuclear Plant, Unit 2, as documented in inspection report 50-316/84-13.

It has come to our attention that the report issued as a result of this inspection contains an error, incorrectly identifying the "as found" containment leakage acceptance criteria as 1.0 La. The correct acceptance criteria is 0.75 La or 0.1875 weight percent per day. A copy of the corrected page is attached. Please update your records to reflect the correct acceptance criteria.

We appreciate your cooperation.

Sincerely,

"original signed by W. S. Little"

W. S. Little, Chief
Engineering Branch

Enclosure: As Stated

cc w/encl:
W. G. Smith, Jr., Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office

RIII <i>SH</i> Hare/lc 11/8/84 11/9/84	RIII <i>W</i> Wright 11/9/84	RIII <i>W</i> Reyes	RIII <i>W</i> Little 11/12
--	---------------------------------------	---------------------------	-------------------------------------

8411190362 841113
PDR ADOCK 05000316
Q PDR

*DMB
IE01
11*