In Reply Refer To:

Dockets: 50-313/84-29

50-368/84-29

Arkansas Power & Light Company ATTN: John M. Griffin, Senior Vice President - Energy Supply P. O. Box 551 Little Rock, Arkansas 72203

Gentlemen:

Thank you for your letter of December 27, 1984, in response to our letter and Notice of Violation dated November 27, 1984. As a result of our review, we find that additional information, as discussed with Mr. Levine and members of your staff in a meeting at the ANO site on January 18, 1985, is required. Specifically, the following should be addressed for item A of NRC Report 50-313/84-29; 50-368/84-29:

- The basis for the violation involving installation of cable tray covers was the failure to maintain the plant configuration in accordance with the requirements stated on design drawings. AP&L's response should discuss what measures AP&L intends to take to ensure the plant is maintained as required by design drawings.
- The evaluation performed by AP&L states that the cable tray covers do not fulfill a safety function; therefore, are not required to be installed for plant safety. AP&L should provide information as to what action will be taken to revise baseline design documents to reflect the results of the tray cover evaluation.

Please provide the supplemental information with 30 days of the date of this letter.

Sincerely,

"Original Signed By: D. R. HUNTER" D. R. Hunter, Chief Reactor Project Branch 2

J. M. Levine, General Manager Arkansas Nuclear One P. O. Box 608 Russellville, Arkansas 72801

bcc: (see page 2)

RPB2 DRHunter/vs 1/1 /85

8503110225 85030 ADDCK 05000313 bcc to DMB (IE01)

bcc distrib. by RIV:

RPB2 G. Vissing, NRR RIV File
R. Lee, NRR MIS SYSTEM

Resident Inspector

D. Weiss, LFMB (AR-2015) ARKANSAS STATE DEPT. HEALTH

Section Chief (RPB2/A)

R. Denise, DRS&P RSTS Operator

Enforcement Officer