NAC For	. 3								LIC	ENSE	E EVE	NT RE	PORT	(LER)			ON BMC	8Y COMMIS	SION
ACILIT	Y N.	AME	(1)											Ø	OCKET NUMBER	(2)		PAGE	
Wash	hi	ngt	on	Nu	clean	r P	lant -	Unit	2	-			-	0	15 0 0	030	9 17	1 OF	1L
		tio	n (of	React	tor	Water	Clea	nun							a fa se de la			
EVENT DATE ISI												ES INVOLVED (S)							
MONTH	1	YAC	YE	AR	YEAR		SEQUENTIAL NUMBER	REV	MBER	MONTH	DAY	YEAR	FACILITY NAME		ES	0 15 10 10 10 1 1			
	-											ł				0 101	- 1-		
01	1	1	8	5	8 5		0009	-0	11	012	28	8 5				0 151	0 10	1011	1
	ERA	TING	-			POR		D PURSU	ANT T	TO THE P		INTE OF 10	CFR §: /0	Check one or more at	the following) (1				
	001			2	20	4021	b 1			20.408			XL	50.73(e)(2)(iv)			1(b)		
POWER LEVEL (10) 0:01			. 7	20.406(a)(1)(ii) 7 20.406(a)(1)(ii)				-	50.36(e)(1) 50.73(e)(2)(v) 50.36(e)(2) 50.73(e)(2)(vi)					X				et	
				20.405(a)(1)(iii) 20.405(a)(1)(iii) 20.405(a)(1)(iv)				-	50.36(c)(2) 50.73(a)(2)(vir) 50.73(a)(2)(i) 50.73(a)(2)(viri)(A 60.73(a)(2)(ii) 50.73(a)(2)(viri)(B										
														kang dia					
			1		20	406	#7(1)(v))(2)(iii)			50.73(a)(2)(x)					
VAME									1	ICENSEE	CONTACT	FOR THIS	LER (12)		1	TELEPHON	E NUMB	IER	
AAME															AREA CODE				
R.	ι.	K	en	ias	. Cor	nol	iance E	nain	eer		1.0		1.18		51019	317	71-	1 2 54	21
						-	COMPLETE	ONE LIN	EFOR	EACH C	OMPONEN	FAILURE	DESCRIBE	D IN THIS REPORT	Enor	2279			
CAUSE	ist	STE		Oste 1	NENT		TURER	TO NP	ROS			CAUSE	SYSTEM	COMPONENT	MANUFAC. TURER	TO NP			
В	1	0.1	1	1	FIT	P	131619		N			1		1.1.1	111				
0	T	41	T		8	T		1											
	L	1	L	1	i	1	111	1				1				1-1	MONTH	DAY	YEAP
							SUPPLEM	ENTAL RI	EPORT	EXPECT	ED I14				EXPECT SUBMISS	ON			
	5 1		cump	ere E	XPECTES	500	WISSION DAT	E/		T	X NO				DATE II	51	1		1
a s	pu	ri	ous	RW	ICU h	i gh	delta	flow	tr	ip.	Isola	tion	of RWO	n (RWCU) i CU is an E n January	SF actua	tion.			to
			B5C PDF 5	31	105 ADO	13	85022 05000	8 397 DR								1			

i

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OM8 NO 3150-0104 EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER YUMBER (6)	PAGE (3)			
		YEAR SEQUENTIAL REVISION NUMBER NUMBER				
Washington Nuclear Plant - Unit 2	0 15 10 10 10 13 19 17	8 5 -0 p 9 - 01	0 12 0 0 12			
Washington Nuclear Flanc - onic 2	0 5 0 0 0 0 0	<u>PPI PPI PI PI</u>				

Plant Condition

a) Plant Mode - 2

b) Power Level - 7%

Event

IRC Form 386A

During reactor plant heatup, the RWCU system was lined up to blowdown to the main condenser. Blowdown flow in excess of the guidelines established by plant procedures was established which caused RWCU delta flow to exceed the trip point of 58.5 GP.4. Blowdown flow was not reduced after receiving the high delta flow alarm, due to other demands on the operator during the Plant startup, and the 45 sec. time delay was exceeded, which actuated an NSSSS isolation signal, resulting in closure of RWCU-V-1 and RWCU-V-4.

Immediate Corrective Action

Operators verified that no actual leak existed, the isolation signals for RWCU-V-1 and RWCU-V-4 were reset and the RWCU system was returned to service, with reduced blowdown flow.

Further Corrective Action

None required

Safety Significance

The occurrence of this event did not affect the safety of the plant or that of the public. The system functioned to isolate in accordance with its design basis and no actual leak existed in the RWCU system.

Similar Events

See LER Nos: 84-035; 84-072-01; 84-072-02; 84-072-03; 84-097; 84-101, 84-119 & 85-010

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397

18

February 28, 1985

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2 LICENSEE EVENT REPORT NO. 85-009-01

Dear Sir:

Transmitted herewith is Licensee Event Report No. 85-009-01 for WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73, discusses the item of reportability, corrective action taken, and action taken to preclude recurrence (and corrects the cause code reported in 85-009).

Very truly yours,

CM. Powers for

J. D. Martin (M/D 927M) WNP-2 Plant Manager

JDM:mm

Enclosure: Licensee Event Report No. 85-009-01

cc: Mr. John B. Martin, NRC - Region V Mr. A. D. Toth, NRC - Site (901A) Ms. Dottie Sherman, ANI INPO Records Center - Atlanta, GA

1EZZ