

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

November 9, 1984


Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Unit 1  
Docket No. 50-369  
LER 369/84-25

Gentlemen:

Pursuant to 10 CFR50.73 (a)(1) and (d), attached is Licensee Event Report 369/84-25 concerning a vent valve in the containment spray system which was found open. This event, which was discovered in June of 1984, was initially determined to be not reportable due to the "minimal impact on its (the containment spray system) design function." (quote from IE Inspection Report 50-369/84-21). This event has been identified in this inspection report as a procedural violation, severity level IV. In addition IE Inspection Report 50-369/84-29 identified this item as reportable. While no identification of the applicable reportability criteria was given, this report is submitted for your information.

Very truly yours,



Hal B. Tucker

SAG/mjf

Attachment

cc: Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

M&M Nuclear Consultants  
1221 Avenue of the Americas  
New York, New York 10020

8411200565 841109  
PDR ADOCK 05000369  
S PDR

IE22  
1/1

Document Control Desk  
November 9, 1984  
Page Two

cc: Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

American Nuclear Insurers  
c/o Dottie Sherman, ANI Library  
The Exchange, Suite 245  
270 Farmington Avenue  
Farmington, CT 06032