

Duquesne Light Company

Beaver Valley Power Station
PO Box 4
Shippingport, PA 15077-0004

JOHN D. SIEBER
Vice President - Nuclear Group

August 4, 1992

4412-3915255

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Subject: Beaver Valley Power Station, Unit No. 2
Docket No. 50-412, License No. NPF-73
Third Refueling Outage Inservice Inspection Report


This letter forwards the Unit 2 Third Refueling Outage Inservice Inspection Report. The following examination results are documented in the attached report:

- ASME Code Class 1, 2, and 3 components for which ASME XI, Article IWA-6230 requires a 90 day report. Included are the results of the neutron flux thimble tube inspections satisfying NRC Bulletin 88-09.
- Steam generator tube inspections for which Technical Specification 4.4.5.5 requires a special report.

These examinations are part of Interval 1, Period 2 of the Unit 2 inservice inspection schedule. The inspections were performed in accordance with Section XI of the ASME Boiler and Pressure Vessel Code, 1983 edition through Summer 1983 addenda.

If you have any questions, please contact Steve Sovick at (412) 393-5211.

Sincerely,


J. D. Sieber

Attachment

cc: Mr. L. W. Rossbach, Sr. Resident Inspector
Mr. T. T. Martin, NRC Region I Administrator
Mr. A. W. De Agazio, Project Manager
Mr. M. L. Bowling (VEPCO) (w/o attachment)

9208120164 920804
PDR ADOCK 05000412
G PDR

AD47