

November 16, 1984

Mr. J. G. Keppler, Regional Administrator U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement 799 Roosevelt Road Glen Ellyn, IL 60137

Subject: Missile Door Calculation Errors W. J. Woolley 10CFR21 (7/5/84)

References: 1) W. J. Woolley letter to J. G. Keppler dated 7/5/84

2) W. J. Woolley letter to J. G. Keppler dated 8/1/84
3) W. J. Woolley letter to J. G. Keppler dated 9/6/84

Dear Mr. Keppler:

This correspondence is to provide an update of the 10CFR21 filed by the W. J. Woolley Company per the above-referenced letters.

With regard to the missile shield doors identified in Reference 1) for the Limerick Generating Station and the Shearon Harris Nuclear Station, the associated calculations and designs have been reconciled with the respective customers and as such, the doors have been qualified as meeting the original project design requirements.

The method of reanalysis, as approved by our customers, utilized more recent publications regarding actual test data as opposed to empirical data used in the original designs.

As a result of the above efforts, we consider the 10CFR21 filed by W. J. Woolley Company on July 5, 1984 to be satisfactorily reconciled and, therefore, anticipate no further action relative to this subject.

If there are any questions, please contact me

Very truly yours,

Justine A. Con

Dwaine A. Godfrey

President

DAG/sls

NOV 19 1984

54-352,353,404