



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

DCB / DCPS

AUG 06 1992

Docket No. 50-346

Centerior Service Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear - Davis-Besse
c/o Toledo Edison Company
300 Madison Avenue
Toledo, OH 43652

Dear Mr. Shelton:

This refers to the inspection conducted by Messrs. W. Levis and R. K. Walton of this office on June 23, 1992, through August 3, 1992, of authorized activities for your Davis-Besse Nuclear Power Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

I. N. Jackiw
I. N. Jackiw, Chief
Reactor Projects Section 3A

Enclosure: Inspection Report
No. 50-346-92011(DRP)

See Attachment Distribution

130037

9208140053 920806
PDR ADDCK 05000346
G PDR

TEO 11

AUG 06 1992

Centerior Service Company

2

cc w/enclosures:

L. Storz, Plant Manager

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

James R. Williams, State of Ohio

Robert E. Owen, Ohio

Department of Health

A. Grandjean, State of Ohio,

Public Utilities Commission