



QUALITY ASSURANCE

FINDING REPORT

5. TYPE:  AUDIT  SURVEILLANCE  NRC NRC  
 NCR  CORRECTIVE ACTION REQ'D.  
 Item of Noncompliance

6. ISSUED TO C.K. Soppe - Project Manager7. ORGANIZATION Bechtel Power Corporation8. THOSE CONTACTED T. Alton - K. Bishop9. 10 CFR 50, APPENDIX B CRITERIA IX1. NUMBER N-093

2. Limerick Units 1 &amp; 2

Project

3. Bechtel Power Corp.

PRIME CONTRACTOR

## 4. REFERENCES


a) AWS D1.1-72 and 72 & 74 editions  
UEC 10/1973

R. A. MULFORD

## 10. FINDING (USE AND REFERENCE ADDITIONAL SHEETS AS REQUIRED)

Two welds from the beam to the clip on beams 23257 and 23239 in unit 2 on Elev. 257 were both incomplete and unacceptable and were made with the aid of a broom stick handle attached to the stinger to reach the joint to be welded; which is contrary to AWS section 3.1.2.

Further, inspection surveillance records indicated that these beam connections were inspected.



## 11. DISCUSSION (USE AND REFERENCE ADDITIONAL SHEETS AS REQUIRED)

Bechtel issued NCR No. 1980 identifying the non-conforming condition.

## 12. RECOMMENDATION (USE AND REFERENCE ADDITIONAL SHEETS AS REQUIRED)

8411270159 840507  
PDR ADOCK 05000352  
PDR  
G

IDENTIFIED	A. Both	Inspector	10/27/76	PE QA REFERENCE ONLY N NO 033 SEC NO. 206 DATE
NAME		TITLE		DATE
IDENTIFIED				DISTRIBUTION A. Teller - TLC P.L. Sauk PLS-6234
NAME		TITLE		
ISSUED BY	J.M. Curran	Site QAE	10/29/76	NAME
		TITLE		DATE

REF 8

SHEET 2 OF



QUALITY ASSURANCE

FINDING REPORT

RECEIVED N-093  
 Limerick Units 1 & 2  
 DEC 10 1978 (14) PROJECT

15. CORRECTIVE ACTION TAKEN TO SOLVE FINDING (USE AND REFERENCE ADDITIONAL SHEETS IF REQUIRED)

1. Issuance of NCR 1980 to acknowledge the nonconforming condition and to acquire dispositioning to correct same.
2. A Reinspection of all other work performed by the particular inspector who accepted the welds in question was accomplished wherever accessible.

1. Disposition on issue 1980 - 11/17/76.  
 2. Various QC-G1 norms C-65-76  
 3. various repair requirs.

ACTION TAKEN BY V.Hilp

NAME

11-22-76 ACTION VERIFIED BY Mark J. Morris

DATE

NAME

DATE

16. CORRECTIVE ACTION TAKEN TO PREVENT RECURRANCE (USE AND REFERENCE ADDITIONAL SHEETS AS REQUIRED)

A training class was held 10-25-76 for re indoctrination and re-orientation in the various aspects of acceptance of completed work, reviewing of inspection criteria and ultimate responsibilities for weld inspections with all personnel in attendance from both the QC and field welding groups.

PCM DIRECTIVE - PCM 239 prohibits use of  
 Broomstick extensions

ACTION TAKEN BY V.Hilp

NAME

11-22-76 ACTION VERIFIED BY Mark J. Morris

DATE

NAME

DATE

17. P.E. ACCEPTANCE OF CORRECTIVE ACTION

- RESOLVES FINDING
- UNACCEPTABLE (SEE SHEET 3 OF 3)
- USE AS IS
- TEMPORARY USE UNTIL RESOLUTION

P.J. Hillman S. Metallurgist 11-22-76  
 (1/1) TITLE DATE



QUALITY ASSURANCE

REF: 8

FILE NUMBER N-093

Limerick Units 1&amp;2

Hired

MCR 28 1077

FINDING REPORT26. REASON UNACCEPTABLE (USE AND REFERENCE ADDITIONAL SHEETS AS REQUIRED)

JAN 1 1977

1. The NCR finding, that generated this MCR, was replied to and ~~be~~ RECEIVED in reference to further commitments by Bechtel Power Corp.
2. This MCR should reflect those further commitments referenced in the above.

Identify the document and contents which indicates all welds that require the use of weld extensions shall be identified and approved by the Lead Weld Engineer.

CJZ

ISSUED BY R.H. Zeng / D.L. Moss

NAME

Sr. Metallurgist

10/16/76

TITLE

DATE

27. REVISED CORRECTIVE ACTION (USE AND REFERENCE ADDITIONAL SHEETS AS REQUIRED)

PCM-246 dated 12-17-76 states that any weld that requires the use of weld extension holders will be identified and approved by the Lead Staff Field Welding Engineer prior to use. This requirement is being incorporated in the latest revision of Job Rule G-16 "Welding".

ACTION TAKEN BY

R.H. Zeng

Date J.R. Rainey, Jr.

ACTION VERIFIED

Date

Date

Date

28. P.E. ACCEPTANCE OF REVISED CORRECTIVE ACTION

RECEIVES FINDING

UNACCEPTABLE (SEE ATTACHED SHEET 3 - OF 3)

AS IS

RECEIVES THIS APPROVAL

P.J. Rainey S.W.G.P. 5-5-77