

APPENDIX A

NOTICE OF VIOLATION

Boston Edison Company
Pilgrim Nuclear Power Station

Docket No. 50-293
License No. DPR-35

As a result of the inspection conducted on August 28, 1984 - October 8, 1984, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

10 CFR 50, Appendix B, VI, requires that measures be established to assure that documents including procedures are reviewed for adequacy and approved for release. Boston Edison Co. Quality Assurance Manual (BEQAM), section 5, "Instructions, Procedures, and Drawings", Revision 11, dated May 14, 1984, requires that the quality assurance program-related procedures listed in Exhibit II-5-1 be reviewed and approved by the Quality Assurance Manager.

Contrary to the above, on September 14, 1984, four procedures listed in Exhibit II-5-1 of the BEQAM were not reviewed and approved by the Quality Assurance Manager.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provision of 10 CFR 2.201, Boston Edison Company is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8411270331 841121
PDR ADOCK 05000293
Q PDR