## **TENNESSEE VALLEY AUTHORITY**

CHATTANOOGA, TENNESSEE 37401 400 Chestnut Street Tower II

BLRD-50-438/84-95 MAR 6 A7:40 March 1, 1985 BLRD-50-439/84-13

U.S. Nuclear Regulatory Commission Region II Attn: Dr. J. Nelson Grace, Regional Administrator 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Dear Dr. Grace:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - A DAPTOR KEYWAY ON 8-INCH BORG-WARNER GLOBE VALVES - BLRD-50-438/84-14, BLRD-50-439/84-13 - SECOND SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector P. E. Fredrickson on January 31, 1984 in accordance with 10 CFR 50.55(e) as NCR 2787. This was followed by our interim reports dated February 29 and July 10, 1984, our final report dated October 25, 1984, and our first supplemental report dated January 4, 1985. Below is our second supplemental report. We consider 10 OFR Part 21 applicable to this deficiency.

As discussed with Inspector A. Ignatonis on February 16, 1985, the date of March 16, 1985 for completion of corrective actions indicated in our first supplemental final report on this matter will not be met. While the work on unit 1 valves has been completed, the work required to meet this commitment for unit 2 has been rescheduled to reflect the change in the overall unit 2 schedule. The corrective action on this matter will be completed by September 26, 1987 for unit 2.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

.a. Nome

forJ. W. Hufham, Manager Licensing and Regulations

cc: Mr. James Taylor, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

8503190390 850301 ADOCK

PDR

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

JE27

An Equal Opportunity Employer