



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
November 15, 1984

FILE: B09-13510C
SERIAL: BSEP/84-2511

NRC Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
LICENSEE EVENT REPORT 1-84-18

Gentlemen:

On October 18, 1984, routine plant surveillance of Unit 1 revealed that the wide flange support beam of hydraulic snubber 1-E11-89SS491 was slightly twisted at the snubber structural attachment. 1-E11-89SS491 restrains a portion of the B Residual Heat Removal Subsystem reactor head spray injection line upstream of the line outboard primary containment isolation valve, 1-E11-F023. The investigation and evaluation of this event is not yet complete. The licensee event report of this event, identified as LER 1-84-18, will be submitted to your office by December 21, 1984.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/clh/LETC1

Enclosure

cc: Mr. R. C. DeYoung
Mr. J. P. O'Reilly

8411280355 841115
PDR ADOCK 05000325
S PDR

IE22
1/0