

APPENDIX A

NOTICE OF VIOLATION

Philadelphia Electric Company
Peach Bottom Atomic Power Station, Units 2 and 3

Docket Nos. 50-277
50-278

As a result of the inspection conducted on August 20-23, 1984, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

- A. Appendix "A" to License Nos. DPR-44 and DPR-56, Technical Specifications Section 6.11, requires that procedures for personnel radiation protection shall be approved, maintained and adhered to for all operations. (1) Procedure HPO/CO-32, "Quality Control of Personnel Dosimetry", requires that a correction factor be calculated for Harshaw dosimetry and used to correct the bias of the Harshaw dosimeter results. (2) Procedure HPO/CO-13E, "Accounting for Lost Badges", requires that there be an evaluation and trending of the loss of dosimetry for major work groups.

Contrary to the above, as of August 23, 1984, (1) correction factors have not been calculated and used to correct the bias of Harshaw dosimeter results and (2) there has been no evaluation or trending of the loss of dosimeters for major work groups.

This is a Severity Level V violation. (Supplement IV)

Pursuant to the provisions of 10 CFR 2.201, Philadelphia Electric Company is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8411280603 841106
PDR ADOCK 05000277
G PDR