

ENCLOSURE 1

NOTICE OF VIOLATION

Alabama Power Company
Farley 2

Docket No. 50-364
License No. NPF-8

The following violations were identified during an inspection conducted on January 11 - February 10, 1985. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criterion VIII, requires measures to be established for identification and control of materials, parts, and components. These measures shall be designed to prevent use of incorrect material, parts and components. Section 8.4.1 of the Operations Quality Assurance Manual requires verification of identification incident to item replacement.

Contrary to the above, measures were not established to verify identification incident to item replacement in that incorrect fusible links were installed on the 2B and 2C containment building coolers.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

FEB 27 1985

Date: _____

8503200031 850227
PDR ADOCK 05000348
Q PDR