

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company  
Brunswick

Docket Nos. 50-325, 50-324  
License Nos. DPR-71, DPR-62

The following violation was identified during an inspection conducted on January 7-11, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50.54 states that the licensee shall have in effect an operator requalification program. Brunswick's operator requal program is implemented by Training Instruction-200, Brunswick Plant Operator Retraining Program. Section 3.2.4 of TI-200 states that any licensed or certified individual that fails a written or operating exam will be removed from licensed duties and placed in an accelerated requalification program. Section 3.2.4.1 of TI-200 states that an annual written examination shall be administered to all licensed and certified personnel each calendar year.

Contrary to the above, one individual did not meet the criteria for passing his annual written exam for the 1984 calendar year. This individual was not removed from licensed duties or placed in an accelerated requalification program.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: February 27, 1985

8503200091 850227  
PDR ADOCK 05000324  
Q PDR