NRC Inspection Report 50-445/446/92-26

bcc to DMB (IEO1) - DRS

1

bcc distrib. by RIV:

J. L. Milhoan
DRP
Lisa Shea, RM/ALF, MS: MNBB 4503
DRSS-FIPS
Project Engineer (DRP/B)
DRS
L. Gilbert
I. Barnes

Resident Inspector (2)
Section Chief (DRP/B)
MIS System
RSTS Operator
RIV File
Chief, Technical Support Section
W. McNeill
L. Ellershaw

RIV:RI:MOPS LGilbert/cjg 8//0/92 RI:MQPS RI:MQPS LEllershaw WMcNeill 8/10/92 8/10/92

C:MQP

D:DRS for D:DRP SJCollins ABBeach 8//3/92

UNITED STATES NUCLEAR REGULATORY COMMISSION REGIONIV 511 RYAN PLAZA DRIVE SUITE 400 ARLINGTON, TEXAS 76011 8064 AUG 2 D 1992 Docket Nos. 50-445 50-446 License No. NPF-87 Construction Permit No. CPPR-127 TU Electric ATTN: W. J. Cahill, Jr., Group Vice President Nuclear Engineering and Operations Skyway Tower 400 North Olive Street, L.B. 81 Dallas, Texas 75201 Gentlemen: SUBJECT: NRC INSPECTION REPORT NOS. 50-445/92-26; 50-446/92-26 This refers to the inspection conducted by Messrs. L. D. Gilbert, L. E. Ellershaw, and W. M. McNeill of this office on July 6-9, and 20-23, 1992. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report. Areas examined during the inspection are identified in the report. These included the comparison of the as-built plant to the description in the Final Safety Analysis Report. During this inspection, it was found that certain of your activities were in violation of NRC requirements. However, in accordance with Section VII.B.1 of the NRC's Enforcement Policy, no citation is being issued for the violation described in paragraph 3.2 of the enclosed inspection report. We have also examined actions you have taken with regard to a previously identified inspection finding. The status of this item is identified in paragraph 2 of the enclosed report. In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room. Should you have any questions concerning this inspection, we will be pleased to discuss them with you. Sincerely, A. Bill Beach, Director Division of Reactor Projects Enclosure: (see next page) 250148

Enclosure: Appendix - NRC Inspection Report 50-445/92-26 w/Attachment 50-446/92-26 w/Attachment

cc w/enclosure:
TU Electric
ATTN: Roger D. Walker, Manager of
Regulatory Affairs for Nuclear
Engineering Organization
Skyway Tower

400 North Olive Street, L.B. 81 Dallas, Texas 75201

Juanita Ellis President - CASE 1426 South Polk Street Dallas, Texas 75224

GDS Associates, Inc. Suite 720 1850 Parkway Place Marietta, Georgia 30067-8237

TU Electric Bethesda Licensing 3 Metro Center, Suite 610 Bethesda, Maryland 20814

Jorden, Schulte, and Burchette ATTN: William A. Burchette, Esq. Counsel for Tex-La Electric Cooperative of Texas 1025 Thomas Jefferson St., N.W. Washington, D.C. 20007

Newman & Holtzinger, P.C. ATTN: Jack R. Newman, Esq. 1615 L. Street, N.W. Suite 1000 Washington, D.C. 20036

Texas Department of Labor & Standards ATTN: G. R. Bynog, Program Manager/ Chief Inspector Boiler Division P.O. Box 12157, Capitol Station Austin, Texas 78711 TU Electric

Honorable Dale McPherson County Judge P.O. Box 851 Glen Rose, Texas 76043

Texas Radiation Control Program Director 1100 West 49th Street Austin, Texas 78756

Owen L. Thero, President Quality Technology Company Lakeview Mobile Home Park, Lot 35 4793 E. Loop 820 South Fort Worth, Texas 76119 NRC Inspection Report 50-445/446/92-26

bcc to DMB (IEO1) - DRS

bcc distrib. by RIV:

J. L. Milhoan
DRP
Lisa Shea, RM/ALF, MS: MNBB 4503
DRSS-FIPS
Project Engineer (DRP/B)
DRS
L. Gilbert
I. Barnes

Resident Inspector (2)
Section Chief (DRP/B)
MIS System
RSTS Operator
RIV File
Chief, Technical Support Section
W. McNeill
L. Ellershaw

RIV:RI:MQPS LGilbert/cjg 8//0/92 RI:MQPS RI:MQPS C:MQPS LEllershaw WMcNeill IBarnes 1/0/92 8/10/92 5/10/92

D:DRS M D:DRP SJCollins ABBeach 8/13/92 10/92