

## UNITED STATES

## NUCLEAR REGULATORY COMMISSION REGION V

1450 MARIA LANE, SUITE 210 WALNUT CREEK, CALIFORNIA 94596

OCT 26 1984

J. D. Shiffer, Vice President Nuclear Power Generation Pacific Gas and Electric Company 77 Beale Street San Francisco, CA 94106

DESIGNATED ORIGINAL Certified By Cot noack

Dear Sir:

The allegations listed below are being resubmitted to PG&E for a more detailed evaluation, investigation, and response.

> 806 919

Attached is a characterization of each allegation file system that provides the specific allegation information.

For each specific allegation or concern forwarded by this letter, the NRC must be apprised, in writing, of the results of the PG&E investigation, the necessary corrective action, and the expected completion date. We request that your responses by titled with the appropriate allegation or concern number. Your responses will be evaluated by the staff for clarity, comprehensiveness, and substance. The responses are subject to verification by the staff. You will be advised of the staff's position upon completion of the staff's evaluation. Your written response is required within 30 days of receipt of this letter.

If you have any questions, or require additional information, please call the Region V office.

Sincerely,

D. F. Kirsch, Acting Director Division of Reactor Safety & Projects

Enclosure: As stated

bcc: D. Kirsch

T. Crowley

8411290626 841028

WED LABOR.

- 806 "An individual took some liberties in buying off welds on the fuel handling building crane rails." The subject welds were on the crane rail restraint plates. the welds were covered with slag and, after chipping off the slag, excessive undercuts and poorly shapen, unequal legs were found.
- 919 "Pullman Power Products: Missing heat log numbers and lack of material traceability via heat numbers, e.g., heat number indicates one-inch metal, whereas, actually is three-quarters." Also, heat number log, when started, started at number 500 rather than number 1.