

ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company  
Catawba Unit 1

Docket No. 50-413  
License No. NPF-35

The following violation was identified during an inspection conducted on January 28 - February 1, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 3.7.11 requires all penetration fire barriers protecting safety-related areas to be functional at all times. With one or more of the penetration fire barriers non-functional, a continuous fire watch is required to be established on at least one side of the affected penetration within one hour. Fire doors in fire barriers are penetration fire barriers and must be maintained functional or a fire watch established.

Contrary to the above, fire door S-400 was not identified as a non-functional fire penetration between the period of January 29 - 30, 1985. This fire door was blocked open and compensatory measures were not established as required in Technical Specifications.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: FEB 27 1985

8503200583 850227  
PDR ADOCK 05000413  
PDR  
Q