

**DUKE POWER COMPANY**

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

July 25, 1984

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Re: RII:GNH/JLK/RRM  
50-413/83-42  
50-414/83-35

Dear Mr. O'Reilly:

Emergency Preparedness items identified in the subject Inspection Report were to have been corrected or resolved prior to exceeding 5% reactor power. Most of the items identified in this report were closed by Inspectors J. L. Kreh and A. L. Cunningham in the recent Inspection Report 413/84-54; 414/84-24. The remaining open items are either ready for NRC reinspection or will be ready for review, as required, prior to exceeding 5% power.

Mr. Bill Cline, Section Chief of the Region II Emergency Preparedness Section, in a July 3, 1984 conversation with M. E. Bolch, Station Emergency Preparedness Coordinator, stated that due to manpower shortages, there would be no reinspection of these items until after October 1, 1984. Mr. Cline also stated there were no emergency planning issues that would prevent escalation above 5% power. Based on this discussion with Mr. Cline, it is our understanding that any further questions arising from the reinspection in October which might require additional time to clear will not impact escalation above 5% power.

Very truly yours,

*H. B. Tucker / BT*

Hal B. Tucker

LTP/rhs

cc: NRC Resident Inspector  
Catawba Nuclear Station

Mr. Robert Guild, Esq.  
Attorney-at-Law  
P. O. Box 12097

Palmetto Alliance  
2135½ Devine Street  
Columbia, South Carolina 29205

Mr. Jesse L. Riley  
Carolina Environmental Study Group  
854 Henley Place  
Charlotte, North Carolina 28207

8412010178 840725  
PDR ADDCK 05000413  
G PDR

IEO1 1/0