



PECO ENERGY

Robert W. Boyce
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
215 327 1200 Ext. 2000

T.S. 6.9.2

December 28, 1995

Docket Nos. 50-352
50-353
License Nos. NPF-39
NPF-85

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: Limerick Generating Station, Units 1 and 2
Special Reports for Two Valid Emergency
Diesel Generator Test Failures

REFERENCE: Technical Specifications Sections 4.8.1.1.3 and
6.9.2

Attached are two Special Reports being submitted pursuant to the requirements of Technical Specifications (TS) Section 6.9.2 as required by TS Surveillance Requirement 4.8.1.1.3. TS Surveillance Requirement 4.8.1.1.3 requires reporting of all diesel generator failures, whether valid or non-valid, within 30 days. The reports are required to include the information recommended in Regulatory Position C.3.b of Regulatory Guide (RG) 1.108, "Periodic Testing of Diesel Generator Units as On-site Electric Power Systems at Nuclear Power Plants," Revision 1, August 1977.

Attachments 1 and 2 provide our responses to the valid failures of the Unit 1 D14 Emergency Diesel Generator (EDG) and the Unit 2 D21 EDG respectively. Both EDG failures resulted from crankcase pressurization transients.

If there are any questions, please do not hesitate to contact Mr. James L. Kantner at (610) 718-3400.

Very truly yours,

Michael P. Gallagher for RWB

SMM\DMS

Attachments

cc: T. T. Martin, Administrator Region I, USNRC (w/attachments)
N. S. Perry, USNRC Senior Resident Inspector, LGS ("")

9601020291 951228
PDR ADOCK 05000352
S PDR
UZULUB

IE22
11

December 28, 1995

Page 2

bcc: D. M. Smith - 63C-3
D. Fetters - 63C-3
W. G. MacFarland - SMB1-1
M. P. Gallagher - SSB3-1
J. L. Kantner - SMB3-1
G. A. Hunger/NRB - 63C-5
J. B. Cotton - 53A-1
C. A. Mengers - SSB4-3
C. B. Anders - SMB3-2
Commitment Coordinator - 62A-1
DER BRP Inspector - SMB3-1
Correspondence Release Point - SMB1-2