

DHB

MAR 07 1985

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Richard P. Crouse
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. M. Phillips and T. Ploski of this office on February 20-22, 1985, of activities at Davis-Besse Nuclear Power Station, authorized by NRC Operating License No. NPF-3, and to the discussion of our findings with Mr. T. Murray and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

8503210142 850307
PDR ADOCK 05000346
G PDR


IE-35
11

Toledo Edison Company

2 MAR 07 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



C. J. Paperiello, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection Report
No. 50-346/85-006(DRSS)

cc w/encl:

S. Quennoz, Station
Superintendent

DMB/Document Control Desk (RIDS)

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of Ohio


Robert H. Quillin, Ohio

Department of Health


D. Matthews, EPB, OIE

W. Weaver, FEMA, RV


RIII


Ploski/lid
02/28/85


RIII


Phillips

RIII


Jackiw

RIII


Paperiello
3/5/85