

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE 2

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 50-361/95-25
50-362/95-25

Operating License: NPF-10
NPF-15

Licensee: Southern California Edison Company
Irvine Operations Center
23 Parker Street
Irvine, California 92718

Facility Name: San Onofre Nuclear Generating Station, Units 1, 2, and 3

Inspection At: Camp Pendleton, California

Inspection Conducted: November 6-9, 1995

Inspector: A. B. Earnest, Physical Security Specialist
Plant Support Branch

Accompanying Personnel: David Orrik and two contractors
Office of Nuclear Reactor Regulation

Approved: Blaine Murray
Blaine Murray, Chief, Plant Support Branch
Division of Reactor Safety

12/19/95
Date

Inspection Summary

Areas Inspected: Routine, inspection of the licensee's physical security program. The areas inspected included protected area detection aids, compensatory measures, access control, test and maintenance, assessment aids, and review of previous inspection findings.

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Results:

Plant Support

- A violation was identified in the area of protected area detection aids. Seven zones were defeated during testing activities (Section 1.1).
- A violation was identified in the area of compensatory measures. The posted officer could not properly observe the compensated protected area barrier (Section 1.2).
- An inspection followup item was identified in the area of access control. An observation was noted concerning personnel access control during heavy traffic periods (Section 1.3).
- The test and maintenance program was adequate (Section 1.4).
- An inspection followup item was identified in the area of protected area assessment. It was observed that towers along the seawall had blind spots because mirrors were fogged-over and dirty (Section 1.5).

Summary of Inspection Findings:

- Violation 361/9525-01; 362/9525-01 was opened (Section 1.1).
- Violation 361/9525-02; 362/9525-02 was opened and closed (Section 1.2).
- Inspection Followup Item 361/9525-03; 362/9525-03 was opened (Section 1.3).
- Inspection Followup Item 361/9525-04; 362/9525-04 was opened (Section 1.5).
- Violation 361/9515-02; 362/9515-02 remains open (Section 2.1).
- Violation 361/9515-01; 362/9515-01 was closed (Section 2.2).

Attachment:

- Attachment - Persons contacted and exit meeting.