

Docket Nos. 50-348
and 50-364

March 11, 1985

DISTRIBUTION

Mr. R. P. McDonald
Senior Vice President
Alabama Power Company
Post Office Box 2641
Birmingham, Alabama 35291

| | |
|-------------|-----------|
| Docket File | NRC PDR |
| L PDR | ORB#1 Rdg |
| HThompson | OELD |
| EJordan | BGrimes |
| JPartlow | CParrish |
| EReeves | ACRS 10 |
| Gray File | TAlexion |
| RAuluck | DLasher |
| JHoppins | DBeckham |
| JStevens | |

Dear Mr. McDonald:

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION FOLLOWING PRELIMINARY
STAFF REVIEW OF LICENSEE RESPONSES TO GENERIC LETTER 83-28
JOSEPH M. FARLEY NUCLEAR PLANT, UNIT NOS. 1 AND 2

The staff has completed a preliminary review to assess the completeness and adequacy of licensee responses to Generic Letter 83-28 Items 2.1, 2.2, 3.1.3, 3.2.3, 4.4 and 4.5. For the Farley Units, your responses were found to be incomplete for Items 2.2.1, 2.2.2, 3.2.3 and 4.5.3. Brief descriptions of the deficiencies are given as guidelines for corrective action in the enclosed request for additional information. Efforts by Owners Groups, INPO and NSSS Vendors have been or are being made to produce generic responses that may be useful in meeting the requirements of Generic Letter 83-28 Items 2.2.2 and 4.5.3. You may wish to contact your Owner's Group or INPO regarding the applicability of such generic responses to your Farley Units.

In order to preserve our present review schedule, the staff needs to have the supplementary information within 60 days for Items (2.2.1, 2.2.2), and within 90 days after NRC completes its review of WCAP-10271 and Supplement 1 for Item 4.5.3. We request your cooperation in meeting this schedule.

This request for additional information was approved by the Office of Management and Budget under clearance number 3150-0011 which expires April 30, 1985. Comments on burden and duplication may be directed to the Office of Management and Budget, Reports Management Room 3208, New Executive Office Building, Washington, D. C. 20503.

Sincerely,

/s/SVarga

Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Enclosure:
Request for Additional
Information

ORB#1:DL
EReeves:fs
3/11/85

CC-ORB#1-DL
SVarga
3/11/85

8503260042 850311
PDR ADOCK 05000348
P PDR

Mr. P. P. McDonald
Alabama Power Company

Joseph M. Farley Nuclear Plant
Units 1 and 2

cc: Mr. W. O. Whitt
Executive Vice President
Alabama Power Company
Post Office Box 2641
Birmingham, Alabama 35291

Mr. Louis B. Long, General Manager
Southern Company Services, Inc.
Post Office Box 2625
Birmingham, Alabama 35202

Houston County Commission
Dothan, Alabama 36301

George F. Trowbridge, Esquire
Shaw, Pittman, Potts and Trowbridge
1800 M Street, N.W.
Washington, DC 20036

Chairman
Houston County Commission
Dothan, Alabama 36301

Robert A. Buettner, Esquire
Balch, Bingham, Baker, Hawthorne,
Williams and Ward
Post Office Box 306
Birmingham, Alabama 35201

Resident Inspector
U.S. Nuclear Regulatory Commission
Post Office Box 24 - Route 2
Columbia, Alabama 36319

State Department of Public Health
ATTN: State Health Officer
State Office Building
Montgomery, Alabama 36104

Regional Radiation Representative
EPA Region IV
345 Courtland Street, N.E.
Atlanta, GA 30308

D. Biard MacGuineas, Esquire
Volpe, Boskey and Lyons
918 16th Street, N.W.
Washington, DC 20006

Charles R. Lowman
Alabama Electric Corporation
Post Office Box 550
Andalusia, Alabama 36420

James P. O'Reilly
Regional Administrator - Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 2900
Atlanta, GA 30303

Ira L. Myers, M.D.
State Health Officer
State Department of Public Health
State Office Building
Montgomery, Alabama 36130

REQUEST FOR ADDITIONAL INFORMATION

GENERIC LETTER 83-28

JOSEPH M. FARLEY NUCLEAR PLANT, UNITS 1 AND 2

Item 2.2.1 - Incomplete

Licensee needs to submit information on how equipment will be classified as safety-related and will be designated as such in plant documentation as requested in sub-items 2.2.1.1 to 2.2.1.6.

Item 2.2.2 - Incomplete

Licensee needs to present his evaluation of the NUTAC program and describe how it will be implemented at FARLEY 1&2. The staff found the NUTAC program fails to address the concern about establishing and maintaining an interface between all vendors of safety-related equipment and the utility. Accordingly the licensee will need to supplement his response to address this concern. This additional information should describe how current procedures will be modified and new ones initiated to meet each element of item 2.2.2 concern.

Item 3.2.3 - Incomplete

Results of review of test and maintenance programs shall identify any post-maintenance testing that may degrade rather than enhance safety and shall describe actions to be taken including submitting needed Technical Specification changes.

Item 4.5.3 - Incomplete

Licensee needs to submit description of the specific implementation plan for FARLEY 1&2 after NRC reviews the WCAP-10271 and supplement 1.