

APPENDIX A  
NOTICE OF DEVIATION

Baltimore Gas and Electric Company  
Calvert Cliffs Nuclear Power Plant  
Unit Nos. 1 and 2

Docket Nos. 50-317  
50-318

As a result of the inspection conducted on October 1-5, 1984, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), published in the Federal Register on March 8, 1984 (49 FR 8583), the following deviation was identified:

NRC/IE Bulletin 79-14 states that the actual configuration of Category I piping systems should be inspected and verified for agreement with the corresponding seismic analysis. Baltimore Gas and Electric Company, in a letter dated July 31, 1979, committed to complete the inspection on all accessible and inaccessible systems, including the reactor coolant system as required by the bulletin no later than the next scheduled outage in the spring of 1980.

Contrary to the above, the piping systems identified as the reactor coolant and the pressurizer surge lines have not been inspected and verified for agreement with the corresponding seismic analysis on Calvert Cliffs Unit Nos. 1 and 2.

Pursuant to the provisions of 10 CFR 2.201, Baltimore Gas and Electric Company is hereby requested to submit to this office within twenty five days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further deviations and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8412040144 841129  
PDR ADOCK 05000317  
Q PDR