


POST OFFICE BOX 2951 · BEAUMONT. TEXAS 77704

AREA CODE 409 838 6631

March 15, 1985 RBG- 20437 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:



River Bend Station Unit 1 Docket No. 50-458 Final Report/DR-157

Gulf States Utilities Company (GSU) has completed its evaluation of DR-157 concerning field-purchased pipe fittings that had been painted externally and internally by various vendors. Based on systems analysis, the quantity and physical distribution of the coating would not prevent the systems involved from performing their intended safety function. GSU has therefore determined this condition is not reportable under 10CFR50.55(e).

Sincerely,

J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

WEB/PJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

4568

8504030067 850315 PDR ADOCK 05000458 S PDR IE-27 1/0