TNRC-85013

TEXAS UTILITIES GENERATING COMPANY

P. O. BOX 2300 . GLEN ROSE, TEXAS 76043

J. C. KUYKENDALL MANAGER NUCLEAR OPERATIONS

April 8, 1985



9045

Mr. Dorwin Hunter U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

SUBJECT: Status of the Emergency Response Facility (ERF) Computer System and the RM-21 Dose Assessment Computer System

Dear Mr. Hunter:

In keeping with Mr. Jim Montgomery's request to ensure your office is informed of the status of the RM-21 and ERF computer systems, we have provided the attached status sheet concerning these systems.

If you have any questions or require additional information, please contact Mr. Jay Laughlin at 817/897-4856, extension 3756.

Sincerely,

They knowlell

JCK:sjb

85.158

Attachments

cc: Messrs. J. B. Baird D. L. Kelley

4160401

PIMS

TNRC-85013 ATTACHMENT

ERF

SUBJECT: Status of the Emergency Response Facility (ERF) Computer System and the RM-21 Dose Assessment Computer System

SystemStatusRM-21Has been turned over to CPSES Operations.
Programs for maintenance, operation, cali-.
bration, and training on this system are
in effect.

Scheduled turnover date is June 1, 1985. Turnover has been delayed due to equipment problems. Please refer to the attached copy of TXX-4447 which provides additional information concerning these problems. Programs for maintenance, operation, calibration, and training have been developed and either have been or are ready to be placed in effect upon system turnover.

TEXAS UTILITIES GENERATING COMPANY

SKYWAY TOWER + 400 NORTH OLIVE STREET, L.B. 81 + DALLAS, TEXAS 75201

BILLY R. CLEMENTS

March 25, 1985 TXX-4447

Mr. D.R. Hunter, Chief Reactor Project Branch 2 U.S. Nuclear Regulatory Commission Office of Inspection & Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76012

Docket No.: 50-445 50-446

COMANCHE PEAK STEAM ELECTRIC STATION ERF COMPUTER TERMINATION POINTS QA FILE: CP-85-06, SDAR-167 FILE NO.: 10110

Dear Mr. Hunter:

On February 1, 1985 we verbally notified your Mr. D. Hunnicutt of a deficiency regarding termination points that have been found to be cracked or broken. We have submitted an interim report logged TXX-4423 dated February 25, 1985.

We have completed our investigation and concluded that the matter is not reportable under 10CFR50.55(e). Records supporting this determination are available for your inspector's review at the CPSES site.

Very truly yours,

BulyRelements

BRC:tlg

cc: NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies) U.S. Nuclear Regulatory Commission Washington, DC 20555

8-54-4248

RECEIVED MAR 2 6 1985 OPERATIONS SUPPORT

A DIVISION OF TEXAS UTILITIES ELECTRIC COMPANY