TENNESSEE VALLEY AUTHORITY

CHATTANOOGA. TENNESSEE 37401
400 Chestnut Street Tower II

3 P | : 22 November 28, 1984

/82-20
/82-18

BLRD-50-438/82-20 BLRD-50-439/82-18

U.S. Nuclear Regulatory Commission Region II Attn: Mr. James P. O'Reilly, Regional Administrator 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - OMISSIONS TO AUXILIARY FEEDWATER PUMP DRAWINGS - BLRD-50-438/82-20, BLRD-50-439/82-18 - SEVENTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on February 25, 1983 in accordance with 10 CFR 50.55(e) as NRC BLN BLP 8207. This was followed by our interim reports dated March 25, July 20, September 7, and December 14, 1982, and April 6 and December 5, 1983. Below is our seventh interim report. We expect to submit our next report by May 15, 1985.

The auxiliary feedwater pump vent, drains, and turbine cooling water interconnecting piping analysis referenced in our sixth report has been completed for unit 1. The unit 2 analysis is currently being reviewed. Further information will be provided in our next report.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. W. Hurham, Manager Licensing and Regulations

cc: Mr. Richard C. DeYoung, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

> Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

8412130609 841128 PDR ADDCK 05000438 PDR

IE2710