December 20, 1984

DMB

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE -- PNO-IV-84-30B

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by NRC staff on this date.

FACILITY:	Public Service Co. of Colorado Fort St. Vrain Platteville, Colorado Docket No. 50-267	Licensee Emergency Classification: Notification of Unusual Event Alert Site Area Emergency		
		General Emergency X Not Applicable		

SUBJECT: UPDATE ON DIESEL GENERATORS

The licensee has completed the repair of the C engine. The problem was a faulty temperature switch on the exhaust gas header and not the thermocouple as earlier suspected. A similar failure occurred on the A engine and its temperature switch was also replaced.

Following the repair, both diesel generator sets were started and loaded at 100% for 2 hours (per the weekly operability surveillance) and have now been declared operable.

The loss-of-offsite power simulation surveillance will be run, probably later today, following unrelated maintenance on a battery charger.

This information is current as of 11:30 a.m. CST.

CONTACT: E. H. Johnson (728-8141) or R. E. Ireland (728-8138).

DISTRIBUTION: H. ST. Chmn Palladino Comm. Zech Comm. Roberts Comm. Asselstine Comm. Bernthal SECY ACRS	MNBB EDO PA MPA ELD	Phillips NRR DCS <u>Air Rights</u> SP	E/W IE OIA AEOD VIB	Willste NMSS RES	MAIL: DOT: Trans Only DMB (Original) INPO 3:10 NSAC 3:14
CA PDR Regions:				Licensee:	

(Reactor Licensees)

DRSP ZOD RPDenise/1k 12/20/84 Por

Martin 20/84

8501030305 841220 PDR I&E PND-IV-84-030B PDR