



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V

1450 MARIA LANE
WALNUT CREEK, CALIFORNIA 94596-5368

JUN 09 1992

Docket No. 50-288

Reed College
Portland, OR 97202-8199

Attention: Dr. William Haden, President

SUBJECT: NRC INSPECTION

Dear Dr. Haden:

This refers to the special inspection conducted by Mr. P. Qualls of this office on April 3 - 24, 1992, of activities authorized by NRC License No. R-112 and to the discussion of our findings held by the inspectors with Mr. Pollock, at the conclusion of the inspection. This report also refers to telephone conversations with Mr. Pollock and Mr. Terdal throughout the inspection period.

This was a special inspection of the Reed College fuel recovery program subsequent to the event at Reed Reactor Facility on November 23, 1991. Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interview with personnel, and observations by the inspectors.

No violations of NRC requirements were identified within the scope of this inspection.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,

James H. Reese, Chief
Safeguards, Emergency Preparedness,
and Non-Power Reactor Branch

Enclosure: Inspection Report No. 50-288/92-01

cc w/enclosure

Dr. Douglas Bennett, Reed College
Mr. J. Michael Pollock, RRF
Dr. William Vernetson, Director of Nuclear Facilities,
University of Florida

9207150322 920609
PDR ADOCK 05000288
G PDR

IECH