

NRC Form 386
(9-83)

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/85

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Grand Gulf Nuclear Station - Unit 1 DOCKET NUMBER (2) 0 5 0 0 0 4 1 6 1 OF 0 2

TITLE (4) Fire Watch Not Performed

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
1	2	8	8	4	061	0	0	0	NA		0 5 0 0 0
											0 5 0 0 0

OPERATING MODE (9) 4

POWER LEVEL (10) 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)
<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.405(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12) NAME Angela H. Horton/License Engineer TELEPHONE NUMBER 6 0 1 4 3 7 - 2 1 4 9

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	KIP	DIRZ	ZZZZ	NO					

SUPPLEMENTAL REPORT EXPECTED (14) YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

The person performing the fire watch patrol became locked in the RHR "A" Piping Room because the door handle on the inside of door 1A204 was broken. She did not have a radio and was apparently unable to contact anyone.

IF 22
1/1

8502050010 850128
PDR ADOCK 05000416
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Grand Gulf Nuclear Station - Unit 1	DOCKET NUMBER (2) 05000411684	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
						02 OF 02

TEXT (If more space is required, use additional NRC Form 306A's) (17)

Description of Reportable Occurrence

On December 28, 1984, between 0100 and 0200 hours, hourly fire watches for the 93 foot and the 119 foot levels of the Auxiliary Building were not performed as required by Technical Specifications.

Initial Conditions

The plant was shutdown. The door handle to room 1A203 was broken.

Status of Redundant or Backup Systems

Not applicable.

Nature of Occurrence

The person performing the fire watch patrol became locked in the RHR "A" Piping Room (1A203) because the door handle on the inside of door 1A204 was broken. She did not have a radio and was apparently unable to contact anyone. A supervisor was sent to locate her when she did not return from the fire watch patrol. He found her approximately 1.5 hours later.

Immediate Corrective Action

Security was informed of the problem and was instructed to have fire watch persons notify them before entry or exit of the area.

Apparent Cause

A metal machine screw on the door handle failed.

Supplemental Corrective Action

The door handle was replaced.

Safety Assessment

No safety consequences.



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

January 28, 1985

NUCLEAR LICENSING & SAFETY DEPARTMENT

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Gentlemen:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-29
File: 0260/L-835.0
Fire Watch Not Performed
LER 84-061-0
AECM-85/0029

Attached is Licensee Event Report (LER) 84-61-0 which is a final report.

Yours truly,

for
L. F. Dale
Director

EBS/SHH:rg
Attachment

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/a)
Mr. N. S. Reynolds (w/a)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. J. P. O'Reilly, Regional Administrator (w/a)
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30323

IE22
1/1