## JAN 1 6 1985

Duke Power Company
ATTN: Mr. H. B. Tucker, Vice President
Nuclear Production Department
422 South Church Street
Charlotte, NC 28242

Gentlemen:

SUBJECT: REPORT NOS. 50-269/84-30, 50-270/84-29 AND 50-287/84-32

In the subject report, our Notice of Violation transmitted one Severity Level V violation with two examples. The assigned severity level for the noted violation should have been reported as Severity Level IV (Supplement IV). In addition, the "Details" of NRC Inspection Report Nos. 50-269/84-30, 50-270/84-29 and 50-287/84-32 list a second violation identified by numbers 50-269/84-30-02, 50-270/84-29-02 and 50-287/84-32-02. To correct this inconsistency, the Notice of Violation has been corrected to agree with the report details. Enclosed are the original pages and the corrected pages of the subject Notice of Violation. Please substitute the corrected pages in your copy of NRC Report Nos. 50-269/84-30, 50-270/84-29, and 50-287/84-32. Dates of the required responses are based on the issuance date of this corrected Notice of Violation.

We regret any inconvenience these corrections may have caused you.

Sincerely,

Original Signed by John A. Olshinski

John A. Olshinski, Director Division of Reactor Projects

Enclosures:

1. Corrected Pages of NOV

Original Pages of NOV

cc w/encls:

M. S. Tuckman, Station Manager

bcc w/encls: State of South Carolina Senior Resident Inspector Document Control Desk

GKuzo 1/0/85 DMontgomery

DCollins 1/ 0/85

AM ( JPStohr 1/9/85 Algratonis 111

VBrownlee

8502050186 850116 PDR ADDCK 05000269 Q PDR Z Goil