The information on this page is considered to be appropriate for public disclosure pursuant to 10 CFR 2.790.

> U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

> > REGION V

Report No. 70-1257/85-01 (IE-V-669)

Docket No. 70-1257

License No. SNM-1227

Safeguards Group III

Licensee: Exxon Nuclear Company, Inc. 2101 Horn Rapids Road Richland, Washington 99352

Facility Name: Exxon Nuclear Fuel Fabrication Facility

Inspection at: Horn Rapids Road Facility, Richland, Washington

Inspection conducted: January 7-11, 1985

m

Date of Last Material Control and Accounting Inspection: November 26-30, 1984

Type of Inspection: Routine Unannounced MC&A Safeguards

Inspectors:

3 helson

Approved by:

502050526 850 DR ADOCK 0700

1-28-85 Date Signed

M. Douglas Schuster, Chief, Safeguards Section Nuclear Materials Safety and Safeguards Branch

Inspection Summary:

<u>Areas Inspected</u>: Facility organization and management controls, facility operations and internal controls, measurement control and statictics and MC&A for imports and exports. The inspection involved 34 inspector hours onsite during regular hours by one NRC inspector.

Results: There were no violations noted in the four areas inspected.