

JAN 29 1985

APPENDIX A

NOTICE OF VIOLATION

Baltimore Gas and Electric Company
Calvert Cliffs Nuclear Power Plant

Docket Nos. 50-317 and 50-318
License Nos. DPR-53 and DPR-69

As a result of the inspection conducted on November 26-30, 1984, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) as revised, 49 FR 8583 (March 8, 1984), the following violation was identified:

Technical Specification 6.8, "Procedures," requires that procedures be established, implemented and maintained. Procedure No. RSP No. 1-106, "Special Work Permit," developed pursuant to the above, states, "The purpose of the Special Work Permit is to specify and describe the radiological controls associated with the operation to be performed..."

Special Work Permit (SWP) No. 84-018, issued on November 1, 1984 covering "entries into the controlled area to perform minor maintenance in areas..." where radiation and contamination levels were very low, contained certain protective clothing requirements, and it also contained the requirement for personnel working on the SWP to check in with the Rad-Con Shift Supervisor.

Contrary to the above, on November 27, 1984, at least three contractor personnel performing minor maintenance activities under SWP No. 84-018 on the 5' elevation near the Unit 1 East Pen Room, failed to comply with the SWP requirements in that they did not contact the Rad-Con Shift Supervisor prior to starting their work activities, and they did not wear the specified protective clothing.

This is a Severity Level IV violation (Supplement V).

Pursuant to the provisions of 10 CFR 2.201, Baltimore Gas and Electric Company is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8502050561 850129
PDR ADOCK 05000317
G PDR

OFFICIAL RECORD COPY

DL50-317/84-13 - 0003.0.0
01/04/85