ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company Catawba Docket No. 50-413 License No. NPF-24

The following violation was identified during an inspection conducted on October 23-26, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criterion V, requires that activities affecting quality be prescribed by documented instructions, procedures or drawings...and shall be accomplished in accordance with these instructions, procedures, and drawings. DPC pipe support/restraint drawings 1-R-ND-0152, Revision 5; 1-R-ND-0265, Revision 3; 1-R-ND-506, Revision 3; DPC Construction Procedure CP-385; and QA procedure M-15 provide installation and inspection requirements for pipe support/restraint numbers 1-R-ND-0152, 1-R-ND-0265 and 1-R-ND-506.

Contrary to the above, 12 noncompliances with procedure and drawing requirements were identified on pipe support/restraint 1-R-ND-506, two noncompliances were identified on 1-R-ND-0265 and one noncompliance was noted on 1-R-ND-0152. 1-R-ND-506 had been inspected and accepted by both construction and nuclear production QC. 1-R-ND-0265 and 1-R-ND-0152 had been inspected and accepted by construction QC.

This is a Severity Level IV violation (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: NOV 2 7 1984