

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company
H. B. Robinson Unit 2

Docket No. 50-261
License No. DPR-23

The following violation was identified during an inspection conducted on July 11 - August 10, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criterion II, as implemented by Section 1 of the licensee's Corporate Quality Assurance Program, requires that activities affecting the quality of safety-related systems and components be accomplished under suitably controlled conditions.

Contrary to the above, as of July 21, 1984, suitable controls were not established during removal of containment sump debris screens in that protective measures were not established to prevent entry of foreign material into the suction piping of both Residual Heat Removal Pumps.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: AUG 16 1984

8502060058 850107
PDR ADOCK 05000261
Q PDR