

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light
H. B. Robinson

Docket No. 50-261
License No. DPR-23

The following violation was identified during an inspection conducted November 6-9, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criteria V and XI, as implemented by the licensee's Corporate Quality Assurance Program requires adherence to procedural measures established for documentation of test results to assure that test requirements have been satisfied.

Contrary to the above, during performance of operational surveillance test procedure OST-162 on November 7, 1984, data recorded for the duration of the sequence for the emergency diesel generators to start and assume the required loads after initiation of a loss of power, combined with a manual safety injection signal, were rounded off instead of recording the actual value obtained from the stopwatch.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: DEC 10 1984

8502060265 850121
PDR ADDCK 05000261
G PDR