

ENCLOSURE 1
NOTICE OF VIOLATION

Duke Power Company
Oconee 3

Docket No. 50-287
License No. DPR-55

The following violation was identified during an inspection conducted on September 11 - October 10, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.4.1 states that the station shall be operated and maintained in accordance with approved procedures. QA Procedure QCK-1 requires that any personnel discovering a nonconforming item shall promptly initiate a nonconforming item report (NCIR) and that production personnel shall initiate NCIR's in accordance with Station Directives.

Contrary to the above requirements, although licensee personnel determined on or about September 5, 1984, that a Cuno filter in the low pressure service water supply line to high pressure injection pump coolers had been installed backwards, an NCIR was not written until September 24. Also, neither Station Directives nor the general employee training program address NCIR's.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

NOV 9 1984

Date: _____

8502060279 850110
PDR ADDCK 05000259
Q PDR