	LICENSEE EVENT REPORT (LER)									U.S. NU	APPROVED OMB NO, 3180-010 W EXPIRES - 6/31/93						
	Y NAME !									Too	CKET NUMBER	(2)	7	DE 131			
		ick	Gene	erating	Stati	07 -	Uni	t 1				10,3,5,					
TITLE F	41		1000										1.101				
Pro	cedu	ral	Def	icienc	y in th	ne Co	ontai	nment	t Atm	ospher	ric Cor	trol V	alve	Te			
EV	ENT DATE	161		PER MAMBER	A (6)	REF	STAG TRO	171		OTHER PA	CILITIES INVOL	VED (8)	aive	10			
MONTH DAY Y		YEAR	YEAR	SEQUENTIAL MEN		ON MONTH DAY YEAR				AQUITY HAME	4	DOCKET NUMBE	AISI	-			
						T						0 151010	101				
1.0	2.0	0.4	0.4				0						1-1-				
1 2	14 8	84	8 4	-0 4	3 - 0	10 11	2 58	15				0 15 10 10	101				
001	DAITAR		THIS RE	ORT IS SUBMIT	TEO PURBUANT	TO THE RE	OUIREMEN	TE OF 18-CF	R & /Cheet		the fatterwings [11]	1	1-1-				
	001 (8)	4		-02(b)		30,4061	-	-	_	,73io)(2)(io)		72,7101					
POWER 0 00		00	29,40614)(1)(8)			80,36tm	111		- N	,736H2Hvl		72,71(4)					
LEVE		90	20.	1811 (114) 800		80,36 lai	(2)		-	.7361(21(wil)		OTHER CS.	melly in Ab				
		÷.,	>a.	106 (a) (7) ((W) 106 (a) (7) ((W) 106 (a) (7) ((W)		90,7368 90,7368 90,7368	(334M) (334M)	DA THIS LES	H:	,73(a)(2)(+80(A) ,73(a)(2)(+80)(8) ,73(a)(2)(a)		3460	in Tont, NA				
AME		-					ONTING! P	on 11116 521	. 1127		1	TELEPHONE NUL	ABER	-			
Jo	hn (. N	agle	, Engi	neer -	Spec	cial	Proje	ects		2, 1, 5	8, 4, 4,	, 5, 1	, 8,4			
	aircea Assurance																
				-		EACH CO	MPONENT P	ALURE DE	CAIRED IN	THIS REPORT	113)						
CAUSE	SYSTEM	courc		-	REPORTABLE TO MPROS	EACH CO	MPOHENT P	CAUSE SY		THIS REPORT	MANUFAC TURER	MEPORTABLE TO MPROS		374			
CAUSE	EVETEM	cour		COMPLET	REPORTABLE	EACH CO	MPOHENT P				MANUFAC						
CAUSE	1	00000		COMPLET	REPORTABLE	EACH CO	MPOHENT				MANUFAC						
CAUSE	EYSTEM	- COUR		COMPLETE MANUFAC TURER	REPORTABLE		7				MANUFAC	TO MPAOS	N.COM	YEAR			

On December 28, 1984, during a review of valve stroke times for trending analysis, the Surveillance Test Coordinator determined that the Surveillance Test, ST-6-057-200-1, Containment Atmospheric Control (CAC) Valve Test, did not properly address the measurement of the stroking time of suppression pool level instrumentation solenoid valve, SV-52-139. As a result, the closure of valve SV-52-139 could not be verified for the period prior to December 28, 1984. The stroke time of this valve was subsequently tested successfully on December 29, 1984. Surveillance Test ST-6-057-200-1 will be revised to require measurement of the stroking time of suppression pool level instrumentation valve SV-52-139 prior to its subsequent quarterly implementation.

8502060340 850125 PDR ADDCK 05000352 S PDR



NAC Farm 364A 19-831	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION													AUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85							
T i max i ale				DOCKET NUMBER (2)								LE	A NUMBI	A (6)			PAGE (3)				
Unit 1	k Generating Station											TEAR	ASEQUENTIAL NUMBER			ALVISION NUMBER			T		
	wired, use sedicional NAC form		0	15	5	0	0	0	3	151	2	8 4	_	0 4	3.	-010	01	2	OF	013	3

Description of the Event:

On December 28, 1984, at approximately 1900, Limerick Generating Station's Surveillance Test Coordinator discovered an administrative error in ST-6-057-200-1, entitled, "Containment Atmospheric Control (CAC) Valve Test" in that the opening time column and closing time column were both identified as not applicable ("N/A") for valve SV-52-139. The purpose of the CAC Valve Test is to demonstrate the operability of each primary containment isolation valve. Section 6.3, 'Action Required', of the surveillance test records the stroking (opening and/or closing) time of forty-seven valves. Review of the results of the previous ST-6-057-200-1 by the ST Coordinator discovered that the measurement of the stroke time of SV-52-139 was exempt by the detail of the test, although Table 3.6.3-1 in the Technical Specifications requires measurement of the closure time for that valve.

Following this discovery, a surveillance test was performed for valve SV-52-139. The valve indicating lights showed the valve in mid-position.

By opening an instrument fitting downstream, it was determined the valve was actually closed. The limit switches were adjusted and the valve was satisfactorily tested on December 29, 1984, with a closing time of 1 second. The Technical Specification maximum allowable closing time for this valve is 6 seconds.

Consequences of the Event:

Although subsequent testing performed on suppression pool level instrumentation valve SV-52-139, December 29, 1984, found this valve to be operable within the Technical Specification requirements, the error within the procedure resulted in an undocumented condition of valve SV-52-139. Valve SV-52-139 is a normally opened valve and is designed to remain open to measure post-LOCA suppression pool level. This valve would be closed in the event of a break of the instrument line between the valve and its associated level transmitter. It was demonstrated that this valve would have performed its intended function.

A-2

NRC Form 366A (9-83)	LICENSEE	U.S.	NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/86									
FACILITY NAME (1)			DOCKET NUMBER (2)		LE	R NUMBE	R (6)	100		PAGE (3)		
	Generating	Station		YEAR		SEQUENT	IAL		REVISION NUMBER			
Unit 1			0 5 0 0 0 3 5 2	8 14	_	0 14	3	_	010	0 3	OF	0013

Cause of the Event:

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The failure to measure the closure time of the outboard isolation valve SV-52-139 of the suppression pool level instrumentation, as required by the surveillance requirements of the Technical Specifications, was caused by an unintentional procedural deficiency in Surveillance Test ST-6-057-200-1, which originated as a typographical error which was not discovered.

Corrective Actions:

As an immediate action to insure similar events do not occur, a review of all valve test surveillance tests was performed. This review revealed no additional procedural deficiencies. As stated in the Description of the Event, the closure time of solenoid valve SV-52-139 was measured and found to be in compliance on December 29, 1984. The Surveillance Test ST-6-057-200-1 was revised and is currently awaiting approval by the facility's Plant Operational Review Committee.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

January 25, 1985

Docket No. 50-352

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

SUBJECT:

Licensee Event Report

Limerick Generating Station - Unit 1

This LER concerns the discovery of a procedural deficiency in the Containment Atmospheric Control Valve Test Surveillance Test for complying with the surveillance requirements of Technical Specification 4.6.3.1.

Reference:

Docket No. 50-352

Report Number:

84-043

Revision Number:

00

Event Date: Report Date: December 28, 1984

Facility:

January 25, 1985

Limerick Generating Station P.O. Box A, Sanatoga, PA 19464

This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(i).

Very truly yours,

W. T. Ullrich

Superintendent

Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator, Region I, USNRC J. T. Wiggins, Senior Site Inspector See Service List

cc: Judge Helen F. Hoyt Judge Jerry Harbour Judge Richard F. Cole Troy B. Conner, Jr., Esq. Ann P. Hodgdon, Esq. Mr. Frank R. Romano Mr. Robert L. Anthony Ms. Phyllis Zitner Charles W. Elliott, Esq. Zori G. Ferkin, Esq. Mr. Thomas Gerusky Director, Penna. Emergency Management Agency Angus Love, Esq. David Wersan, Esq. Robert J. Sugarman, Esq. Martha W. Bush, Esq. Spence W. Perry, Esq. Jay M. Gutierrez, Esq. Atomic Safety & Licensing Appeal Board Atomic Safety & Licensing Board Panel Docket & Service Section (3 Copies) James Wiggins Timothy R. S. Campbell