

ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company
Catawba

Docket Nos. 50-413 and 50-414
License Nos. NPF-24 and CPPR-117

The following violation was identified during an inspection conducted on March 13 - August 24, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criterion II, Quality Assurance Program requires, in part, that the applicant shall regularly review the status and adequacy of the Quality Assurance program, and that management of other organizations participating in the Quality Assurance program shall regularly review the status and adequacy of that part of the Quality Assurance Program which they are executing.

Contrary to the above, the Quality Assurance Program in the area of welding, was apparently not reviewed for adequacy in that a welding foreman and his supervisor were able to create an environment which led some workers on the foreman's crew to perceive that QA requirements could be suspended to complete specific assignments.

This is a Severity Level IV violation (Supplement II).

8502060396 840831
PDR ADOCK 0500C413
G PDR