

APPENDIX A

NOTICE OF VIOLATION

Duquesne Light Company
Beaver Valley Power Station, Unit 2

Docket No. 50-412
License No. CPPR-105

As a result of the inspection conducted on November 20, 1984 - January 2, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register Notice on March 8, 1984 (49 FR 8583), the following violation was identified:

10 CFR 50, Appendix B, Criterion V requires that activities affecting quality shall be prescribed by procedures and shall be accomplished in accordance with these procedures.

Specification 2BVS-981 requires Level "C" storage to be maintained for reactor coolant system piping and valves to protect this equipment from exposure to the environment and airborne contaminants.

Contrary to the above, certain piping and valve items in a 3-inch reactor coolant system bypass line for the "B" loop were not properly sealed to protect this equipment from exposure to the environment and airborne contaminants.

This is a Severity Level IV Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Duquesne Light Company is hereby required to submit to this office within thirty days of the date of the cover letter to this Notice, a written statement or explanation in reply including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending your response time.

8502060536 850128
PDR ADOCK 05000412
Q PDR

OFFICIAL RECORD COPY

50-412/84-18 AP A - 0001.0.0
01/17/85