

POST OFFICE BOX 2951 · BEAUMONT. TEXAS 77704 AREACODE 409 838 6631

> January 21, 1985 RBG-19962 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

12-27

110

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-275

An interim or final status report concerning the welded studs for the variable inlet vane assembly on four fans supplied by Buffalo Forge Company for the Standby Gas Treatment System and Fuel Building charcoal filtration units will be provided by February 7, 1985.

Sincerely,

L. A. England

J. E. Booker Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8502060552 850121 PDR ADOCK 05000458 S PDR