

Wayne H. Jens
Vice President
Nuclear Operations

img

**Detroit
Edison**

Fermi-2
6400 North Dixie Highway
Newport, Michigan 48166
(313) 586-4150

January 15, 1985
EF2-70232

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

- Reference: (1) Fermi 2
NRC Docket No. 50-341
- (2) Letter, D. A. Wells to J. G. Keppler
February 6, 1984, QA-84-0079
- (3) Letter, W. H. Jens to J. G. Keppler
July 5, 1984, EF2-69272
- (4) Letter, W. H. Jens to J. G. Keppler
November 30, 1984, EF2-70219

Subject: Amended Report of 10CFR50.55(e)
Item lll, "Design Deficiency on
the RHR Reservoir Freeze Over"

Detroit Edison will use a temporary auxiliary boiler to add any heat necessary to prevent freezing of the Residual Heat Removal Service Water (RHRSW) reservoirs this winter. Therefore, Detroit Edison will not operate the Emergency Diesel Generators to supply heat to the RHRSW reservoirs as had been indicated in References (3) and (4).

If you have any questions concerning this matter, please contact Mr. Lewis Bregni, (313) 586-5083.

Sincerely,



cc: P. M. Byron
R. C. DeYoung
R. C. Knop
M. D. Lynch
USNRC, Document Control Desk
Washington, D.C. 20555

8502060561 850115
PDR ADOCK 05000341
S PDR

JAN 25 1985

IE27
/0