


POST OFFICE BOX 2951 + BEAUMONT, TEXAS 77704


AREA CODE 409 838 6631

January 24, 1985 RBG-19960 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:





An interim or final status report concerning trunnion welds on pipe support components supplied by B. F. Shaw Company will be provided by February 7, 1985.

Sincerely,

L.a. England

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8502060576 850124 PDR ADDCK 05000458 S PDR