## FACILITY OPERATING LICENSE NO. NPF-68

DOCKET NO. 50-424

AND

TO LICENSE AMENDMENT NO. 31

FACILITY OPERATING LICENSE NO. NPF-81

DOCKET NO. 50-425

Replace the following pages of the Appendix "A" Technical Specifications with the enclosed pages. The revised pages are identified by Amendment number and contain vertical lines indicating the areas of change.

| REMOVE PAGES | INSERT PAGES |
|--------------|--------------|
| 3/4 7-15     | 3/4 7-15     |
| 3/4 7-16     | 3/4 7-16     |
| 3/4 7-18     | 3/4 7-18     |
| 3/4 9-15     | 3/4 9-15     |
| 3/4 9-16     | 3/4 9-16     |
| B 3/4 7-4    | B 3/4 7-4    |
| B 3/4 7-5*   | B 3/4 7-5*   |
| B 3/4 7-5a*  | B 3/4 7-5a*  |
| B 3/4 9-3    | B 3/4 9-3    |

<sup>\*</sup> overflow pages, no changes

- Verifying that the system maintains the control room at a positive pressure of greater than or equal to 1/8 inch Water Gauge at less than or equal to a pressurization flow of 1500 cfm relative to adjacent areas during system operation and
- 4) Verifying that the heaters dissipate a minimum of 95 kW when tested in accordance with Section 14 of ANSI N510-1980;
- f. After each complete or partial replacement of a HEPA filter bank, by verifying that the HEPA filter banks remove greater than or equal to 99.95% of the DOP when they are tested in place in accordance with Section 10 of ANSI N510-1980 while operating the system at a flow rate of 19,000 cfm  $\pm$  10%; and
- g. After each complete or partial replacement of a charcoal adsorber bank, by verifying that the charcoal absorbers remove greater than or equal to 99.95% of a halogenated hydrocarbon refrigerant test gas when tested in-place in accordance with Section 12 of ANSI No10-1980 while operating the system at a flow rate of 19,000 fm  $\pm$  10%.

3/4 7-16

- Werifying that the system maintains the spent fuel storage pool area at a slightly negative pressure relative to the outside atmosphere during system operation, and
- 4) Verifying that the heaters dissipate a minimum of 16 kW when tested in accordance with Section 14 of ANSI N510-1980.
- e. After each complete or partial replacement of a HEPA filter bank, by verifying that the HEPA filter banks remove greater than or equal to 99% of the DOP when tested in-place in accordance with Section 10 of ANSI N510-1980 while operating the system at a flow rate of 5000 cfm ± 10%.
- f. After each complete or partial replacement of a charcoal adsorber bank, by verifying that the charcoal absorbers remove greater than or equal to 99% of a halogenated hydrocarbon refrigerant test gas when they are tested in-place in accordance with Section 12 of ANSI N510-1980 while operating the system at a flow rate of 5000 cfm ± 10%.

DISTRIBUTION:
Docket File
NRC & Local PDRs
PD I1-3 R/F
Vogtle R/F

S. Varga D. Matthews L. Berry D. Hood

OGC-WF

D. Hagan

G. Hill (8)
W. Jones
C. Grimes
ACRS (10)
GPA/PA
OC/LFMB

14-E-4

14-H-25

14-H-25

14-H-25

15-B-18

MNBB 4702

P1-37 MNBB 7103

11-F-23

P-135

17-F-2

MNBB 4702