

09623

7/16/92
13:29:19

RMS/DOCUMENT DISTRIBUTION CENTER (DDC)

DISTRIBUTION TRANSMITTAL/ACKNOWLEDGEMENT

STATION LEVEL 2

RECIPIENT/LOCATION: USNRC - ATTN DDC CONTRL DESK **MAIL OUT LIST**

STATION NO: 483

ISSUE DATE: 07/16/92 TRANSMITTAL NO: Y03887

DOCUMENT NO./AMEND NO. UNIT SHEET REV COPIES INSTRUCTION

OGAP-01.00			05	1	
JCN ICM0310	0				ERT

INSTRUCTIONS:

FOLLOW THE INSTRUCTIONS ABOVE, SIGN, DATE AND RETURN THIS DOCUMENT DISTRIBUTION TRANSMITTAL/ACKNOWLEDGEMENT TO DC (N1002) WITHIN 10 WORK DAYS FROM THE ISSUE DATE. IF ANY QUESTIONS CALL EXT. 7715.

SIGNATURE OF RECIPIENT

DATE

STPEGS MAILING ADDRESS:

STPEGS
RMS/DC - N1002
P. O. BOX 289
WADSWORTH, TEXAS 77463

9207230286 920716
PDR AJNCK 05000498
P PDR

JEH3

LICENSING DOCUMENT CHANGE REQUEST FORM (TYPICAL)

(Page 1 of 1)

R3887

Change Number QA-010 Date 06/23/92

Originator C.L. HARVEY Dept QA


Change Description DELETE VICE PRESIDENT, NUCLEAR SUPPORT
AND REFLECT GENERAL MANAGER, INFORMATION RESOURCE
AS A DIRECT REPORT TO GROUP VICE PRESIDENT, NUCLOM.

Initiating Documentation ANNOUNCEMENT OF ORGANIZATION
CHANGE

Unit(s) Affected: Unit 1 _____ Unit 2 _____

Implementation Status: Unit 1 Completion Date _____

Unit 2 Completion Date _____



Reviewed by _____
(if applicable) Manager, Environmental Department Date _____

Reviewed and Approved by _____
Supervising Engineer, Nuclear Licensing Date _____

Reviewed by _____
(OQAP changes only) General Manager, Nuclear Assurance Date 7/10/92

Reviewed and Approved by _____
(OQAP changes only) Group Vice President, Nuclear Date 7/15/92

Change Incorporated in Revision Number _____ of the _____

Verified by _____
Signature Date _____

SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION OPERATIONS QUALITY ASSURANCE PLAN ORGANIZATION	NUMBER	REV. NO.
	Chapter 1.0	5
	PAGE 4 OF 8	
	EFFECTIVE DATE 12-21-90	

5.1.3.3 The Manager, Design Engineering is responsible for establishment and maintenance of the plant design bases and plant configuration. Design Engineering issues plant modifications, resolves plant nonconformances, approves special process procedures and supports the ASME XI Inservice Inspection Program.

The Manager, Design Engineering, reports to the Vice President, Nuclear Engineering.

5.1.3.4 The Manager, Nuclear Engineering is responsible for nuclear fuel design, fuel acquisition, fuel management, probabilistic risk assessment, thermal-hydraulic analysis and the shift technical advisor program.

The Manager, Nuclear Engineering reports to the Vice President, Nuclear Engineering.

5.1.4 The General Manager, Information Resources, is responsible for assuring that activities associated with the distribution of documents, the records management system, plant communications, and the administrative computer systems are in compliance with the OCAP.

5.1.4.1 The General Manager, Information Resources, reports to the Group Vice President, Nuclear.

GA-004

GA-010

SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION OPERATIONS QUALITY ASSURANCE PLAN ORGANIZATION	NUMBER	REV. NO.
	Chapter 1.0	5
	PAGE 7 OF 8	
	EFFECTIVE DATE	12-21-90

ATTACHMENT I

HOUSTON LIGHTING & POWER COMPANY
NUCLEAR GROUP - QA FUNCTIONS




CHART DEPICTS REPORTING RELATIONSHIPS ONLY

OPERATIONS QUALITY ASSURANCE PLAN

TABLE OF CONTENTS

PAGE - 1

BOOK 1

DOCUMENT NO	REV SUPPLEMENT	DOCUMENT TITLE	DATE IN EFFECT
QQAP-00.00	05	DEFINITIONS	12/21/90
QQAP-01.00	05	ORGANIZATION	12/21/90
QQAP-01.00	05 ICN ICN0504	ORGANIZATION	1/15/92
QQAP-01.00	05 ICN ICN0506	ORGANIZATION	5/19/92
QQAP-01.00	05 ICN ICN0508	ORGANIZATION	5/19/92
QQAP-01.00	05 ICN ICN0509	ORGANIZATION	6/11/92
QQAP-01.00	05 ICN ICN0510	ORGANIZATION	7/16/92
QQAP-02.00	07	PROGRAM DESCRIPTION	12/20/91
QQAP-02.00	07 ICN ICN0707	PROGRAM DESCRIPTION	3/19/92
QQAP-02.00	07 ICN ICN0709	PROGRAM DESCRIPTION	6/11/92
QQAP-03.00	06	CONDUCT OF PLANT OPERATIONS	12/20/91
QQAP-04.00	04	QUALIFICATION, TRAINING & CERTIFICATION OF PERSONNEL	12/21/90
QQAP-05.00	04	MAINT, INSTALLATION OF MODIFICATIONS & ACTIVITIES	12/21/90
QQAP-06.00	05	DESIGN & MODIFICATION CONTROL	12/21/90
QQAP-07.00	05	PROCUREMENT	12/21/90
QQAP-08.00	04	CONTROL & ISSUANCE OF DOCUMENTS	12/21/90
QQAP-09.00	05	CONTROL OF MATERIAL	12/20/91
QQAP-10.00	06	INSPECTION	12/21/90
QQAP-11.00	05	TEST CONTROL	12/21/90
QQAP-12.00	05	INSTRUMENT & CALIBRATION CONTROL	12/21/90
QQAP-13.00	05	DEFICIENCY CONTROL	12/20/91
QQAP-14.00	04	RECORDS CONTROL	12/21/90
QQAP-15.00	04	QUALITY ASSURANCE AUDIT & SURVEILLANCE	12/21/90
QQAP-16.00	04	NUCLEAR FUEL MANAGEMENT	12/21/90
QQAP-17.00	04	ASME SECTION XI REPAIRS & REPLACEMENTS	12/21/90
QQAP-18.00	04	ASME SECTION XI EXAMINATION & TESTING	12/21/90

SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION OPERATIONS QUALITY ASSURANCE PLAN TABLE OF CONTENTS	NUMBER Table of Contents	REV. NO. 9
	PAGE 1 OF 2	
	EFFECTIVE DATE 12-21-90	

(Updated 6/24/92)

Chapters Requiring NRC Approval

Chapter Number	Title of Chapter	Effective Revision No.	Effective Date	Change Notices
	Definitions	5	12-21-90	
1.0	Organization	5	12-21-90	QA-004 QA-006 QA-008 QA-009 QA-010
2.0	Program Description	7	12-20-91	QA-007 QA-009
3.0	Conduct of Plant Operations	6	12-20-91	
4.0	Qualification, Training, and Certification of Personnel	4	12-21-90	
5.0	Maintenance, Installation of Modifications, and Related Activities	4	12-21-90	
6.0	Design and Modification Control	5	12-21-90	
7.0	Procurement	5	12-21-90	
8.0	Control and Issuance of Documents	4	12-21-90	
9.0	Control of Material	5	12-20-91	
10.0	Inspection	6	12-21-90	
11.0	Test Control	5	12-21-90	
12.0	Instrument and Calibration Control	5	12-21-90	
13.0	Deficiency Control	5	12-20-91	
14.0	Records Control	4	12-21-90	
15.0	Quality Assurance Audit and Surveillance	4	12-21-90	