

4237

Dear Judge Hoyt, here is an updated list of inspection reports and deficiencies. I repeat that these reports mirror a continuing problem on the sight with construction and quality.

INFORMATION FROM INSPECTION REPORTS

M. I. LEWIS  
6504 BRADFORD TERR.  
PHILA., PA. 19149

<u>Report number</u>	<u>Violation</u>	<u>Unresolved items</u>	<u>Open issues</u>	<u>Other</u>
50-352/84-59				discrepancies
84-60 and 84-13				procedures not revised
84-55		x		
84-51			x	
84-56		x		
84-58				
84-50				followup needed
84-49 and 84-12	x			fuel rod procedure not ok'd.
84-46		x		
84-42		x		
84-47		x		
84-29	x	x	x	deficiencies and unacceptable
84-44				test exception
84-27	4	x		
84-33			x	construction deficiency
84-31		x		
84-41				many deficiencies
84331			x	confusing writing
84-36 and 353/84-10		x	x	
84-34				test change notice (TCN)
84-16				lack of communication b/n shifts.
84-35			x	
84-26 and 353 /84-09	2			
Board Notification 84-142				many deficiencies
84-30				deficiencies

Please note that this list only contains letters from NRC to Peco for the months of August, September, October and November. There are issues still being generated and there are issues still open from months and years previous to the letters in the above list. Also the list does not demonstrate all deficiencies in these letters.

DS03

850208039B 850207  
PDR ADOCK 05000352  
G PDR

SERVED FEB 7 1985

85  
FEB - 7 09:18  
SEARCH & SERVICE  
ANCH

M. I. LEWIS  
6504 BRADFORD TERR.  
PHILA., PA. 19149

ONCKET NUMBER  
PROD. & UTIL. P...  
50-352-02  
39-39-002