

Colt Industries



Fairbanks Morse
 Engine Division
 701 Lawton Avenue
 Beloit, Wisconsin 53511
 608/364-4411

January 28, 1985

Office of Inspection & Enforcement
 U. S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, Ill. 60137

Attention: Mr. James G. Keppler, Director, Region III

Subject: Colt Industries-Fairbanks Morse Engine Division
 Emergency Diesel Generators
 Possible Thermostatic Valve Malfunction
 Fail Safe To "Full Cooling Position"
 Part 21 Report
 Supplemental Report No. 8
 Northeast Utilities - Millstone III

References: May 25, 1982; June 28, 1982 and September 17, 1982
 Part 21 Reports - Robertshaw Valves - same subject


Gentlemen:

The lower overrun assemblies in the Robertshaw valves installed on the Diesel Generator Sets at Northeast Utilities - Millstone III have been replaced with overrun assemblies utilizing cotter pins to positively lock the nut to the stem.

The units are now free of the reported potential defect.

A copy of this report is being forwarded to the utility involved.

Very truly yours,


 J. M. Moriarty
 MANAGER UTILITY SALES

JMM:jc

cc: Stone & Webster Engineering Corp.
 P. O. Box 2325
 Boston, Mass. 02107
 Attention: Lead Electrical Engineer
 J.O. No. 12179 (Millstone III)

U. S. Nuclear Regulatory Commission
 c/o Document Management Branch
 Washington, D.C. 20555

Robertshaw Controls Company
 P. O. Box 400
 Knoxville, TN 37901
 Attention: T. T. Howell, Quality Mgr.

8502080467 850128
 PDR ADOCK 05000423
 S PDR

A division of the Colt Industries Operating Corp.

1E19 40
 JAN 30 1985