



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JUL 22 1992

Docket Nos. 50-313
LJ-368
License Nos. DPR-51
NPF-6

Entergy Operations, Inc.
ATTN: Neil S. Carns, Vice President
Operations, Arkansas Nuclear One
Route 3, Box 137G
Russellville, Arkansas 72801

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-313/92-20; 50-368/92-20 (NOTICE OF VIOLATION)

This refers to the system entry retest inspection conducted by Messrs. H. F. Bundy, M. E. Murphy, and Dr. D. A. Powers of this office on June 8-12, 1992. The inspection included a review of activities authorized for your Arkansas Nuclear One, Units 1 and 2, facility. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report and included system entry retest activities for modifications, temporary modifications, and maintenance activities.

During this inspection, it was found that certain of your activities were in violation of NRC requirements. Consequently, you are required to respond to this violation, in writing, in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter. This violation is a concern because failure to utilize the provisions that have been provided for changing the scope or details of safety-related maintenance activities could result in the performance of maintenance steps, which would impact on the safe operation of the facility.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.


9207280052 920722
PDR ADDCK 05000313
Q PDR

10011

In accordance with 10 CFR Part 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,


A. Bill Beach, Director
Division of Reactor Projects

Enclosures:

1. Appendix A - Notice of Violation
2. Appendix B - NRC Inspection Report
50-313/92-20
50-368/92-20

cc w/enclosures:

Entergy Operations, Inc.
ATTN: Donald C. Hintz, President &
Chief Operating Officer
P.O. Box 31995
Jackson, Mississippi 39286

Entergy Operations, Inc.
ATTN: John R. McGaha, Vice President
Operations Support
P.O. Box 31995
Jackson, Mississippi 39286

Wise, Carter, Child & Caraway
ATTN: Robert B. McGehee, Esq.
P.O. Box 651
Jackson, Mississippi 39205

Arkansas Nuclear One
ATTN: Early Ewing, General Manager
Technical Support and Assessment
Route 3, Box 137G
Russellville, Arkansas 72801

Entergy Operations, Inc.
ATTN: Jerry Yelverton, General Manager
Plant Operations
Route 3, Box 137G
Russellville, Arkansas 72801

Entergy Operations, Inc.

-3-

Entergy Operations, Inc.
ATTN: James J. Fisicaro
Director, Licensing
Route 3, Box 137G
Russellville, Arkansas 72801

Honorable Joe W. Phillips
County Judge of Pope County
Pope County Courthouse
Russellville, Arkansas 72801

Winston & Strawn
ATTN: Nicholas S. Reynolds, Esq.
1400 L Street, N.W.
Washington, D.C. 20005-3502

Arkansas Department of Health
ATTN: Ms. Greta Dicus, Director
Division of Radiation Control and
Emergency Management
4815 West Markham Street
Little Rock, Arkansas 72201-3867

B&W Nuclear Technologies
ATTN: Robert B. Borsum
Licensing Representative
1700 Rockville Pike, Suite 525
Rockville, Maryland 20852

Admiral Kinnaird R. McKee, USN (Ret)
214 South Morris Street
Oxford, Maryland 21654

ABB Combustion Engineering
Nuclear Power
ATTN: Charles B. Brinkman
Manager, Washington
Nuclear Operations
12300 Twinbrook Parkway, Suite 330
Rockville, Maryland 20852

bcc to DMB (IE01)
 bcc distrib. by RIV:

J. L. Milhoan
 DRP
 Lisa Shea, RM/ALF, MS: MNBB 4503
 DRSS-FIPS
 Project Engineer (DRP/A)
 DRS
 M. E. Murphy
 D. A. Powers
 G. F. Sanborn, EO

Resident Inspector
 Section Chief (DRP/A)
 MIS System
 RSTS Operator
 RIV File
 Chief, Technical Support Section
 H. F. Bundy

 J. Lieberman, OE, MS: 7-H-5

RIV:TPS <i>[Signature]</i>	RI:TPS <i>[Signature]</i>	RI:TPS <i>[Signature]</i>	C:TPS <i>[Signature]</i>	D:DRS <i>[Signature]</i>	D:DRP
MEMurphy/lb	HFBundy	DAPowers	JL Lieberman	SJCoTrins	ABBeach
7/19/92	7/19/92	7/19/92	7/19/92	7/20/92	7/22/92

bcc to DMB (IE01)
 bcc distrib. by RIV:

J. L. Milhoan
 DRP
 Lisa Shea, RM/ALF, MS: MNBB 4503
 DRSS-FIPS
 Project Engineer (DRP/A)
 DRS
 M. E. Murphy
 D. A. Powers
 G. F. Sanborn, EO

Resident Inspector
 Section Chief (DRP/A)
 MIS System
 RSTS Operator
 RIV File
 Chief, Technical Support Section
 H. F. Bundy

 J. Lieberman, OE, MS: 7-H-5

RIV:TPS <i>[Signature]</i>	RI:TPS <i>[Signature]</i>	RI:TPS <i>[Signature]</i>	C:TPS <i>[Signature]</i>	D:DRS <i>[Signature]</i>	D:DRP
MEMurphy/lb	HFBundy	DAPowers	JLGiardiardo	SJCollins	ABBeach
7/9/92	7/9/92	7/9/92	7/10/92	7/20/92	7/22/92