

APPENDIX A

NOTICE OF VIOLATION

Entergy Operations, Inc.
Arkansas Nuclear One, Unit 1

Docket No. 50-313
License No. DP-51

During an NRC inspection conducted June 8-12, 1992, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

Arkansas Nuclear One, Unit 1, Technical Specification 6.8.1 states, in part, "Written procedures shall be established, implemented, and maintained covering the activities referenced below:

"a. The applicable procedures recommended in Appendix 'A' of Regulatory Guide 1.33, November 1972"

Section I of Appendix A to Regulatory Guide 1.33, November 1972 states, in part, "Maintenance which can affect the performance of safety-related equipment should be properly preplanned and performed in accordance with written procedures, documented instructions, or drawings appropriate to the circumstances" Plant Administrative Procedure 1000.024, Revision 39, Change PC-1, "Control of Maintenance," was issued to control maintenance activities, which affect the performance of safety-related equipment. Procedure 1000.24 states, in part, "If additional work is identified, another job request shall be written or the work scope on the original job order revised to include the additional scope."

Job Order 865242 was issued to cover quality work, which was to be performed on safety-related Load Center Transformer X6.

Contrary to the above, on April 24, 1992, during work on Load Center Transformer X6 pursuant to Job Order 865242, additional work involving installation of heat shrink covering on electrical cables, which was not covered by the original job order, was performed. The work scope on Job Order 865242 was not revised, nor was another job request written, as required by Plant Administrative Procedure 1000.024.

This is a Severity Level IV violation (313/9220-01)(Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Entergy Operations, Inc., is hereby required to submit a written statement or explanation to the Regional Administrator, Region IV, with a copy to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the

date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, the Commission may issue an Order or Demand for Information as to why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas
this 22nd day of July 1992