

October 24, 1983

Note to J. VanVliet

SUBJECT: TMI-1 TESTING OF VALVES & SEALS (OELD # 838 469)

There are some minor editorial changes marked up on the package. In addition, the example does not seem to be correct. The example you refer to relates to situations involving a change in the Regulations which has resulted in the need for minor modification to the license. This doesn't appear to be the case. There is no indication in this package that the change is caused by any change in the Regulations. If that's true, then you need more discussion of the change in the Regulations which caused this change. If not, pick another example or analyze the three factors.

ASMB
for Joe Scinto

8502090010 840518
PDR FOIA
ADAT084-166 PDR