

ENCLOSURE 1

NOTICE OF VIOLATION

Georgia Power Company  
Hatch 2

Docket No. 50-366  
License No. NPF-5

The following violation was identified during an inspection conducted on August 21 - September 20, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1 requires that procedures be established, implemented and maintained covering safety-related activities.

Contrary to the above, on August 25, 1984, procedure HNP-2-3240, Low-Low Set Reactor Instrument Functional Test and Calibration was not properly implemented in that test valve (TV1) and isolation valve (IV1) were not properly aligned during system restoration for instruments 2B31-N120C, 2B21-N120D and 2B21-N122B. The out-of-position valves were signed for as being independently verified in position.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: OCT 09 1984

8503010430 841128  
PDR ADDCK 05000321  
G PDR